



Recommended mounting


direct mounting
using M8 screws



mounting using standard pipe bracket



VNCJ



MOS technik s.r.o.
Jižní 724/14
742 35 Odry

Czech Republic
VAT: CZ29381045




Company office
Nádražní 29
742 35 Odry

tel: +420 602 729 019
e-mail: info@mostechnik.cz

Technical details

Compressed air source


connection: 2x G 1/4"
max. pressure: 8 bar
filtered air: min. 25µm



It is necessary to ensure sufficient supply of compressed air for correct function of the nozzle.

Inlet tubes and fittings must be designed to prevent large pressure losses.

Planchet substitution



It is possible to increase the power of the air stream by planchet substitution. Planchettes are available with thicknesses: 0,05 mm and 0,08 mm. You can also adjust bigger thickness by combination of several planchettes.

Make sure that the **planchet is mounted in the correct position!**